## Reporting Measurement Values

What is the proper way to report a location statistic and its uncertainty?

Someone reports the sulfate measurement error as shown below. How many (ahem) errors can you spot?

$$-0.835\,467\,3 \pm 0.355\,354\,5$$

## Reporting Measurement Values

What is the proper way to report a location statistic and its uncertainty?

Someone reports the sulfate measurement error as shown below. How many (ahem) errors can you spot?

$$-0.835\,467\,3 \pm 0.355\,354\,5$$

- no units
- no indication of what property (population parameter) is being estimated
- the uncertainty measure is not identified
- far too many significant figures

## Reporting Measurement Values

What is the proper way to report a location statistic and its uncertainty?

Someone reports the sulfate measurement error as shown below. How many (ahem) errors can you spot?

$$-0.835\,467\,3 \pm 0.355\,354\,5$$

- no units
- no indication of what property (population parameter) is being estimated
- the uncertainty measure is not identified
- far too many significant figures

Examples of proper reporting of confidence intervals

- $\mu : -0.84 \pm 0.36\,\mathrm{w/w\%}$ (95% CL)

## Reporting Measurement Values

What is the proper way to report a location statistic and its uncertainty?

Someone reports the sulfate measurement error as shown below. How many (ahem) errors can you spot?

$$-0.835\,467\,3 \pm 0.355\,354\,5$$

- no units
- no indication of what property (population parameter) is being estimated
- the uncertainty measure is not identified
- far too many significant figures

Examples of proper reporting of confidence intervals

- $\mu : -0.84 \pm 0.36\,\mathrm{w/w\%}$ (95% CL)
- 95% CI for $\mu : -0.84 \pm 0.36\,\mathrm{w/w\%}$

## Reporting Measurement Values

What is the proper way to report a location statistic and its uncertainty?

Someone reports the sulfate measurement error as shown below. How many (ahem) errors can you spot?

$$-0.835\,467\,3 \pm 0.355\,354\,5$$

- no units
- no indication of what property (population parameter) is being estimated
- the uncertainty measure is not identified
- far too many significant figures

Examples of proper reporting of confidence intervals

- $\mu : -0.84 \pm 0.36\,\text{w/w\%}$ (95% CL)
- 95% CI for $\mu : -0.84 \pm 0.36\,\text{w/w\%}$
- 95% CI for $\mu$: $(-1.19, -0.48)\,\text{w/w\%}$